



Govt. corners identified = +, + . Corners of previous subd. surveys = X. Corners established on this survey = O

| Description of Corners found, or established on this survey. | |
|--|---|
| (1) Gregg affirms that post replaces original iron pin. | (7) Point (6) to (18) are monumented by heavy gauge |
| (2) 3/8" iron pipe set in 5" block of cement. | (8) iron pipe 3/4" dia., 15" long, set 14" in ground, with block of |
| (3) Old 1/2" iron pipe. Replaces iron pipe 3/4" diam. 15" long in cement block. | (9) concrete around; top of pipes have screw caps. |
| (4) Original survey stake. | (10) From corner (3), a nail in a 20" pine tree, blazed and |
| (5) Set pipe 3/4" diam. 15" long in cement block. | (11) scribed B.T. bears N. 29° E. 2.0 ft. |
| (6) Set pipe 3/4" diam. 15" long in cement block and scribed B.T. with nail bears N. 88° 30' W. 16.2 ft. | (12) scribed B.T. bears N. 29° E. 2.0 ft. |

COUNTY SURVEYORS RECORD
GRAND COUNTY, COLORADO.
 Survey by *Frank S. Huntington*, Co. Sur.
 For *Clarence L. & Margaret F. Harrington*
 Date *8/5-6/1943* Scale of Map *1" = 50'*
 Courses *True* Var.
 Measurements *Steel tapes*
 Instruments *Gurley transit*
 Assistants *Clarence L. Harrington*

5 p.m.